

July 29, 2014

To: Affected North American Dealers

Subject: Service Bulletin S14XG 8D Battery Cables Routing

Models Affected: 2010 through 2015 Model Year All American Front and Rear Engine

Models Equipped with Optional 8 D Batteries

Bulletin Duration: One (1) Year from In-Service Date

Overview

On buses with Feature 40142-04 8 D batteries, the positive battery cable may come in contact with the battery compartment door reinforcement when door is closed. Service Bulletin S14XG provides instructions for inspecting and, if needed, for rerouting the battery cables to prevent contact with the compartment door reinforcement.

Affected Units

A printout is attached of the buses in your territory that are affected by this bulletin. Service Bulletin S14XG will be mailed to all owners on record.

Time Allowance

Time allowed to inspect the positive cable for contact with compartment door reinforcement is 0.1 hours per bus.

Time allowed for inspecting the positive battery cable for contact with compartment door reinforcement and rerouting the battery cables is 0.3 hours per bus.

Repair Parts

Replacement positive battery cables must be ordered directly through Blue Bird Service Parts. Parts are available to be ordered.

Labor Reimbursement

Warranty applications for labor reimbursement may be submitted to Blue Bird iWarranty (Campaigns/Claims).

Bulletin Duration

This Service Bulletin ends one (1) year from the in-service date of the affected buses.



Repair Facility

Owners are being advised to contact their dealer for assistance, if needed.

Questions

Questions regarding this bulletin should be directed to your Blue Bird Field Service Representative.

Sincerely,

Bill Coleman

Engineering Services

478-822-2242



July 29, 2014

To:

Select Blue Bird Customers

Subject:

Service Bulletin S14XG 8D Battery Cables Routing

Models Affected:

2010 through 2015 Model Year All American Front and Rear Engine

Models Equipped with Optional 8 D Batteries

Bulletin Duration:

One (1) Year from In-Service Date

Overview

On buses with Feature 40142-04 8 D batteries, the positive battery cable may come in contact with the battery compartment door reinforcement when door is closed. Service Bulletin S14XG provides instructions for inspecting and, if needed, for rerouting the battery cables to prevent contact with the compartment door reinforcement.

Affected Units

The buses in your fleet that are affected by this bulletin are identified by Blue Bird body serial number(s) on the enclosed cover sheet.

Time Allowance

Time allowed to inspect the positive cable for contact with compartment door reinforcement is 0.1 hours per bus.

Time allowed for inspecting the positive battery cable for contact with compartment door reinforcement and rerouting the battery cables is 0.3 hours per bus.

Repair Parts

If needed, replacement positive battery cables must be ordered by your dealer directly through Blue Bird Service Parts. Parts are available to be ordered.

Labor Reimbursement

If you perform this service bulletin yourself or have an outside repair facility perform this bulletin you may submit claims for labor and parts reimbursement to your Blue Bird dealer.



Bulletin Duration

This Service Bulletin ends one (1) year from the in-service date of the subject buses in your fleet.

Repair Facility

We encourage you to contact your Blue Bird dealer to arrange to have this Service Bulletin performed. However, you may have the option to perform this Service Bulletin yourself or have a qualified repair facility convenient to you perform this work. A qualified technician must perform work required under this bulletin.

Questions

Questions regarding this bulletin should be directed to your Blue Bird Dealer.

Sincerely,

Bill Coleman

Engineering Services

13:0 Cleman

478-822-2242



Battery Cable May Contact Battery Compartment Door Reinforcement

BULLETIN

Models Affected: 2010 to 2015 Model Year All American Front and Rear Engine Models

ISSUE

On buses with Feature 40142-04 8 D batteries, the positive battery cable may come in contact with the battery compartment door reinforcement when door is closed.


CORRECTIVE ACTION

Inspect positive cable and, if needed, change routing of battery cables to insure proper clearance. Replace positive battery cable if damaged.

PROCEDURE

WARNING: Always follow all Federal, State, Local and Shop safety standards and use proper safety equipment, and thoroughly read and understand all instructions before performing these procedures.

- 1. Park the bus on a level surface, apply parking brakes, turn off engine and remove keys. Chock wheels.
- 2. Open the battery compartment door and inspect the positive battery cable in the battery box for signs of contact with the battery compartment door reinforcement when closed.




Indicates positive cable is contacting compartment door reinforcement



Battery Cable May Contact Battery Compartment Door Reinforcement



- 3. If contact is observed, Disconnect batteries Note: when disconnecting the batteries, remove the negative cable first.
- 4. Inspect the positive cable for damage.
- 5. If cable insulation has been damaged to the point that stranded wires are exposed, replace the cable and route per the illustration below.
- 6. If cable insulation damage is minor and no stranded wire is exposed, route the negative cable so that it is over the positive cable per illustration below.



Negative Cable Routed Over Top of Positive Cable